Monday, 23/02/2009 10:09:25 AM

User:

Julie Dawson

## **Process Sheet**

Customer

: CU-DAR001 Dart Helicopters Services

Job Number : 45938 **Estimate Number** 

: 13673

P.O. Number

This Issue

Prsht Rev.

First Issue

: 23/02/2009

: NC

: // : 44864

S.O. No. :

Type

Part Number

**Due Date** 

**Drawing Name** 

: D22211

: RIB

**Drawing Number** 

: D2221 REV H (PG.5) **Project Number** 

: N/A : H

**Drawing Revision** 

Material

: 27/02/2009

Qty:

Each 8 Um:

**Previous Run** Written By

Checked & Approved By

Comment

: Est Rev:A

New Issue 08-12-02 DD verified by:EC

: LARGE FAB ASSY

**Additional Product** 

Job Number:



Seq. #:

1.0

**Machine Or Operation:** 

**Description:** 

M304TS0750W065

304 SQ Tube .75x.75x.065W

Comment: Qty.:

8.4000 f(s)/Unit Total:

304 SQ Tube .75x.75x.065W

batch: 7110839

09-02-24

2.0

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESCURCE 1

1- Cut as per dwg D2221

2- Deburr and remove identification markings on tube

INSPECT WORK TO CURRENT STEP

3.0

QC5

67.2000 f(s)



Comment: INSPECT WORK TO CURRENT STEP

4.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: Basket CELL

5.0

FINAL INSPECTION/W/O RELEASE

QC21



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



1 A. M. 25


	Dart	Aer	ospa	ice	Ltd
--	------	-----	------	-----	-----

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No		DAD #1 Foult Cotomonia NO	<b>.</b>	N. DO		<b>D</b>	

Part No:	_ PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
Resolution:		Disposition:	QA: N/C Closed:	Date:

NCR:			WORK ORDE	ER NON-CONFORMAN	CE (NCR)			
DATE	·	Description of NC Section A	Corrective Action Section B			Verification		
	STEP		Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC inspector
							·	
	0							

NOTE: Date & initial all entries



ı